

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Sutter Maintenance Yard Maintenance Area 0017

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lake County Sutter Maintenance Yard - Middle Creek	Left	3.87	03/12/2015 03/12/2015	Bob Duffey

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals				°
					°
DWR ID	DWR_MA0017_01_s _ 2013_7				
Action/Comments					
Inspector Comments: The LMA has the O&M manuals.					

No Photos

LM Start		Rating **	A	Issue No.	8		
LM End		Issue Type +	Ma	Location *	N/A		
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Emergency Supplies & Equipment				°		°
					°		°
DWR ID	DWR_MA0017_01_s _ 2013_8						
Action/Comments							
Inspector Comments: The LMA has adequate flood fight supplies and equipment.							

No Photos

LM Start		Rating **	A	Issue No.	9		
LM End		Issue Type +	Ma	Location *	N/A		
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Flood Preparedness & Training				°		°
					°		°
DWR ID	DWR_MA0017_01_s _ 2013_9						
Action/Comments							
Inspector Comments: The LMA completed flood fight training in 2014.							

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Sutter Maintenance Yard Maintenance Area 0017

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lake County Sutter Maintenance Yard - Middle Creek	Left	3.87	03/12/2015 03/12/2015	Bob Duffey

LM Start	3.80	Rating **	A	Issue No.	476
LM End	3.80	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.144495 °	39.144495 °
				-122.906355 °	-122.906355 °
DWR ID	DWR_MA0017_01_s _ 2015_476				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Sutter Yard sprayed the landside slope.					

Photo 1 of 1 : SP_2015_MA0017_339_476_20150406_00095.jpg



View of the Sprayed slope by Sutter Yard.

LM Start	4.09	Rating **	U	Issue No.	2
LM End	7.23	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.142155 °	39.118735 °
				-122.902343 °	-122.884892 °
DWR ID	DWR_MA0017_01_s _ 2012_2				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

Photo 1 of 1 : SP_2015_MA0017_339_2_20150406_00101.jpg



View of the trees along the waterside slope and toe.

LM Start	4.09	Rating **	A	Issue No.	1
LM End	7.23	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.142155 °	39.118675 °
				-122.902343 °	-122.884772 °
DWR ID	DWR_MA0017_01_s _ 2015_1				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

Photo 1 of 1 : SP_2015_MA0017_339_1_20150406_00100.jpg



View of the native grasses along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--